











1




1 pc

7




30 pcs

13




2 pcs

19



1 pc

A




M8*30 - 16 pcs

G



M14 - 1 pc

2




1 pc

8



30 pcs

14



1 pc

B




M8*40 - 14 pcs

H



M5 - 1 pc

3



1 pc

9



15 pcs

15



1 pc

C




M8 - 14 pcs

J



M8*70 - 2 pcs

4




1 pc

10



4 pcs

16



1 pc

D



M8 - 8 pcs

L



M8*25 - 4 pcs

5



2 sets

11



4 pcs

17



1 pc

E




M8 - 10 pcs

6



2 sets

12



2 pcs

18




1 pc

F




1 pc


STEP 1




STEP 2




STEP 3




STEP 4




STEP 5




STEP 6




STEP 7




STEP 8




STEP 9




STEP 10





STEP 11



STEP 12



STEP 13



STEP 14

