













Ø8x30mm A 30	Ø6x42mm B2 2	Ø15/12mm C 17	Ø12/10mm C5 2	L=20mm D2 19	Ø20 E11 4
L=350mm L R I8 1	Ø20/16mm J44 2	L L 5	Ø6,3x13mm M2 2	Ø6,3x28mm M8 2	Ø4,0x16mm P1 16
Ø3,0x20mm P7 4	L=150mm S 1	M4x22mm F40 4	U U 1		





	Ersatzteil Nummer	Dimension
	OIO.218	480x415x16
	OIO.219	480x415x16
	OIO.112	268x398x16
	OIO.517	268x376x16
	OIO.404	304x375x16
	OIO.617	277x323x2,5
	OIO.618	259x348x2,5
	WST.0134	350x100x12
	WST.0164	350x100x12
	WST.0366	248x100x12
	OIO.710	154x316x16
	OIO.113	268x512x16





1 — 15







1 — 5

16 — 25






1

$\pm 12/10\text{mm}$  C5 2	$\pm 8 \times 30\text{mm}$  A 4
--	---







2

$\pm 6 \times 42\text{mm}$  B2 2











3





$L=20\text{mm}$  D2 2
--



4















5







6




$\pm 8 \times 30 \text{ mm}$  A 26	$\pm 15/12 \text{ mm}$  C 17	$L = 20 \text{ mm}$  D2 11
--	--	--




7




8






9




10











11




12








 L 3	 P7 2
--	---




14



[CD]		±20/16mm	±6,3x13mm	±6.3x28mm
				
L=350mm		J44	M2	M8
1		2	2	2




15




	M4x22mm	±3.0x20mm	±20
			
S	U	P7	E11
1	1	2	4




2.















1.




3.







 A 26	 C 17	 D2 11
$\pm 8 \times 30 \text{mm}$	$\pm 15/12 \text{mm}$	$L = 20 \text{mm}$






17


L=20mm  D2 6	L=150mm  F40 4	4.0x16mm  P1 16
---	---	--




18






19




20











21





22




	
L	P7
3	2






24

 [CD] L=350mm 1	 +20/16mm J44 2	 +6,3x13mm M2 2	 +6.3x28mm M8 2
--	--	--	--



25



 S 1	 M4x22mm U 1	 +3.0x20mm P7 2	 +20 E11 4
---	---	---	--

