

1




5 pcs

2



1 pc

3




5 pcs

4



1 pc

5




1 pc

6




1 pc

7



2 pcs

8



1 pc

9



1 pc

A



M8\*25 mm x 3 pcs

B



M8 x 3 pc

C



M8\*22\*1,5 mm x 3 pcs

D



M6\*20 mm x 4 pcs

E




M6\*15\*1 mm x 2 pcs

F



M6\*35 mm x 6 pcs

G




M6\*20 mm x 4 pcs

H




1 pc


STEP 1




STEP 2




STEP 3




STEP 4



STEP 5



STEP 6



STEP 7

